

## **HISTORIC AMERICAN BUILDINGS SURVEY**

### **INDEX TO PHOTOGRAPHS**

CEDAR CITY AUTOMOTIVE REPAIR SHOP, HOSE WINDING SHED  
820 North Main Street  
Cedar City  
Iron  
Utah

HABS UT-139-D

### **INDEX TO BLACK AND WHITE PHOTOGRAPHS**

Steve Tregeagle, photographer, April 2009

UT-139-D-1	HOSE WINDING SHED, NORTH (FRONT) SIDE, VIEW TO SOUTH.
UT-139-D-2	HOSE WINDING SHED, NORTH (FRONT) SIDE, VIEW TO SOUTH, WITH SCALE.
UT-139-D-3	HOSE WINDING SHED, EAST AND NORTH SIDES, VIEW TO SOUTHWESST.
UT-139-D-4	HOSE WINDING SHED, WEST AND SOUTH SIDES, VIEW TO NORTHEAST.
UT-139-D-5	HOSE WINDING SHED, PINTEL DETAIL.
UT-139-D-6	HOSE WINDING SHED, PINTEL DETAIL, WITH SCALE.
UT-139-D-7	HOSE WINDING SHED, DETAIL OF HOSE REEL.
UT-139-D-8	HOSE WINDING SHED, DETAIL OF HOSE REEL, WITH SCALE.